



Water Bacteriological Analysis

174 04259

Sample: 8237 Gold Run

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Eli

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04259		Sample: 8237 Gold Run					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04260

Sample: 8251 Kendall Rd. (Resource Center)

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Report Date: 1/22/2026

Phone: (360) 306-9301

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Hannah

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04260		Sample: 8251 Kendall Rd. (Resource Center)					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04261

Sample: 8139 Peaceful Valley Ct.

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Report Date: 1/22/2026

Phone: (360) 306-9301

Email: operations.hannah@wcwd13.com

Approved By:

Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Eli

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04261		Sample: 8139 Peaceful Valley Ct.					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04262

Sample: 1131 Deep Valley

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Hannah

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04262		Sample: 1131 Deep Valley					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04263

Sample: 8225 Kendall Rd. (Club House)

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Eli

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04263		Sample: 8225 Kendall Rd. (Club House)					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04264

Sample: 531 Flair Valley

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Hannah

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04264		Sample: 531 Flair Valley					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04265

Sample: 2341 Clear Valley

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:



Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Eli

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04265		Sample: 2341 Clear Valley					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026



Water Bacteriological Analysis

174 04266

Sample: 572 Sprague Valley

Invoice Number: 26-01310

Client: Whatcom County Water District #13

PO Number:

532 Sprague Valley Drive
Maple Falls, WA 98266

Project Name: Main Break Testing

Phone: (360) 306-9301

Report Date: 1/22/2026

Email: operations.hannah@wcwd13.com

Approved By:

Sample Information

Date Collected: 1/21/2026

Date Received: 1/21/2026

Sample Collected by: Eli

Source Number: 0

Sample Purpose: Routine Compliance

Sample Type: Post Treatment/Finished Water Sample

Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing

Suitability: Yes

System Number: 95914

System Name: WHATCOM COUNTY WATER DIST 13

Lab #: 04266		Sample: 572 Sprague Valley					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026
E. COLI	Absent	/100ml	1	SM_9223B	CA	1/22/2026	1/22/2026